

Subject: BROKEN SLING

What's Happened?

When lifting a concrete pipe, the sling broke dropping the pipe to the lorry bed.

How Did It Happen?

The incident is still under investigation.

Recommendations and Lessons to be learnt:

Ensure lifting equipment is:

- Carefully selected
- Suitable for the task

Also ensure that:

- Correct slinging techniques are employed
- You do not combine chains and slings
- Lifting assessments are adhered to at all times



IF IN DOUBT ASK